

### SERVICE BULLETIN

# Change of fuel pressure limit for ROTAX<sub>®</sub> Engine Type 916 i B and 915 i (Series)

ATA System: 73-00-00 Fuel system

## MANDATORY

### 1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods in accordance with prevailing legal regulations.

BRP-Rotax GmbH & Co KG cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

#### 1.1) Applicability

All engines of Series 916 iS B and 915 iS A are affected:

| Engine type | Serial number |
|-------------|---------------|
| 916 iS B    | all           |
| 915 iS A    | all           |

For complete instructions and compliance to this Service Bulletin refer to Service Bulletin-SB-916 i-001 / SB-915 i-010, latest edition section 1.2 onward.

NOTE: Section 1.6) Approval: Is not required for engines of the type UL, iS (Series).

Section 3) Accomplishment: In addition: persons with adequate type-specific training.

**Symbols used** For meaning of the symbols used in this document, see chapter >Safety< of the latest Operators Manual for the respective engine type.

Translation into other languages might be performed in the course of language localization but does not lie within ROTAX' scope of responsibility.

In any case the original text in English language and the metric units are authoritative.

09 September 2021 Initial Issue